BA-103 1783-1790 Hampton National Historic Site

(Hampton Mansion, Hampton Hall) 535 Hampton Lane

Towson

Federal

Hampton Mansion, historically known as Hampton Hall, is a fine example of late Georgian architecture in America. The mansion is situated at the top of a hill and dominates the surrounding landscape. It has a symmetrical five-part linear plan: a large 7-bay-wide 2 1/2-story central structure connected to two 2 1/2-story dependencies with one-story hyphens. The house is constructed of gneiss-schist rubble stone covered with stucco scored to resemble fine coursed ashlar masonry. The original stucco was rusticated with penciled lime joints. The original wood shingle roofing was replaced in the 19th century with slate. On both the north and south facades, the central three bays are covered by a 2 1/2story pedimented portico supported by large square columns. The windows within the portico have shouldered architrave and pediments. On both facades, the portico has a modillioned cornice, a Palladian window in the tympanum, and a finial at the peak. Similar finials stand at the corners of the portico roof and the corners of the main gable roof. On each floor, a central door opens onto the portico; the second floor of the portico has an elaborate Chinese Chippendale balustrade. The first and second floor entrances on both facades are flanked with Doric pilasters, and have open pediments and fanlight windows. On the first floor, the fanlights are filled with 19th century colored glass with the Ridgely coat of arms. Windows are 12/12 sash on the first floor and 8/12 above. A belt course separates the first and second stories. On either side of the portico the roof is

pierced by two elaborate gable-roofed dormers with round-arched windows with tracery. At the center of the ridgeline is a large domed octagonal belvedere with 12/12 sash windows separated by Tuscan columns, and topped by a finial. Two interior chimneys rise from either end of the gable roof. The gable ends of the main block are four bays wide, with a single 8/8 sash window in each of the pedimented attic gables. Between the two chimneys on either end is a traceried false bullseye window with round architrave and keystones. On each face of the hip-roofed dependencies, which are two bays wide on the north and south facades, are a single 8/8 sash gable-roofed dormer window. The easternmost and westernmost of these dormers are false, each containing a single stuccoed chimney stack. The hyphens, three narrow bays wide, are gable roofed, with a front pediment. Each holds a central entrance flanked by 9/9 sash windows. On the interior, the house has a Georgian plan. The wide center hall connects the north and south entrances, with two rooms to either side. The two rooms on the east side are separated by a passage and stairway to the second floor. Floors throughout the house are of pine, and those on the first floor are precisely matched in size. The major rooms have elaborate mantels, cornices, wainscoting, and window architraves. The property also includes an extensive array of support buildings, including an orangery, two stone stables in the vicinity of the house, and a farm complex across the road. Buildings of particular note at the latter site include an 18th century farm manager's house and three slave quarters.

Hampton Hall was built between 1783 and 1790. It was probably designed in collaboration between Captain Charles Ridgely (1733-1790), the owner, and Jehu Howell (?-1787), a highly skilled builder and carpenter. Two of Hampton's inhabitants, Captain Ridgely and his heir and nephew General/Governor Charles Carnan Ridgely (1760-1829) made significant contributions to Maryland's agriculture, industry, and government. Under their direction Hampton developed into one of the largest agricultural plantations in the state. Hampton was owned and managed by the Ridgely family for over 200 years. At the time of its construction in the 1780s, Hampton Mansion was one of the largest Georgian houses in Maryland, and it remains an outstanding example of late Georgian architecture. With its massive size, symmetrical five-part Palladian plan with carefully orchestrated hierarchy of spaces, and its bold yet finely executed ornament, Hampton remains an important example of Georgian architecture in an American country house. Equally significant are the terraced gardens and the array of important support structures. The farm manager's house is a fine example of mid-18th century domestic building, and the three associated slave quarters are the most complete example of antebellum slave housing in the state. Hampton National Historic Site is owned by the National Park Service and is open to the public.

Maryland
Baltimore County
District IX
Dulaney Valley Road, Towson

BA-103 Hampton 0301031204

1790

Built by Charles Ridgely. Late Georgian style, of local stone. Stuccoed, wide portico, large cupola, ornate dormers, etc. Formal gardens, originally.

Part of a 7,000-acre estate once owned by the Ridgely family; lived here 158 years.

Now a National Historic Landmark

In National Register 1968

NO WE FORM EXISTS OF 0/13

(First HABS Report)
E. Frances Offutt
HABS COMMITTEE OF BALTIMORE
COUNTY HISTORICAL SOCIETY

July 29,1965



Hampton -CENTRAL MARCA ID BALTIMORE CO. BA-C/6


Jerry Dadds 11/73

PARK NAME, STATE HAMPTON NATI	ONAL HISTORIC SITE, MARYLAND
STRUCTURE NAME(S): HAMPTON MAN	SION ENTRANCE DRIVE & PARKING LOT
PROPERTY / DISTRICT NAME: HAMPTO	
	MPTON LANE Town / City: TOWSON
Municipality:	County: BALTIMORE PARK Tract #: n/a
DATE BUILT: 1992 LCS:	n/a PARK #:
SIGNIFICANCE National St	tate & Regiona Local
NATIONAL REGISTER CRITERIA A	B C D
NARRATIVE STATEMENT OF SIGNIFICANCE	E
architectural or historical signi	Hampton Mansion and Estate. Structure possesses no ificance.
•	Continuation Sheet?
NARRATIVE DESCRIPTION	
	er for bus parking w/ grassed area for overflow, upper tier
areas. Bus parking area is 85°	' x 40', auto parking at upper tier is 115' x 95'. One culvert " CMP. Total length of entrance drive is approx. 1844'.
areas. Bus parking area is 85 under paved area, a 11" x 18"	' x 40', auto parking at upper tier is 115' x 95'. One culvert " CMP. Total length of entrance drive is approx. 1844'. Continuation Sheet?
areas. Bus parking area is 85 under paved area, a 11" x 18" National Park Service, MARO	' x 40', auto parking at upper tier is 115' x 95'. One culvert " CMP. Total length of entrance drive is approx. 1844'.
areas. Bus parking area is 85 under paved area, a 11" x 18" National Park Service, MARQ Individually Eligibla	' x 40', auto parking at upper tier is 115' x 95'. One culvert " CMP. Total length of entrance drive is approx. 1844'. Continuation Sheet?
areas. Bus parking area is 85 under paved area, a 11" x 18" National Park Service, MARO Individually Eligibla Contributes to:	' x 40', auto parking at upper tier is 115' x 95'. One culvert " CMP. Total length of entrance drive is approx. 1844'. Continuation Sheet? State Historic Preservation Office Comments
areas. Bus parking area is 85 under paved area, a 11" x 18" National Park Service, MARQ Individually Eligibla Contributes to: Property	' x 40', auto parking at upper tier is 115' x 95'. One culvert " CMP. Total length of entrance drive is approx. 1844'. Continuation Sheet?
areas. Bus parking area is 85 under paved area, a 11" x 18" National Park Service, MARO Individually Eligibla Contributes to:	' x 40', auto parking at upper tier is 115' x 95'. One culvert " CMP. Total length of entrance drive is approx. 1844'. Continuation Sheet? State Historic Preservation Office Comments
areas. Bus parking area is 85 under paved area, a 11" x 18" National Park Service, MARQ Individually Eligibla Contributes to: Property	' x 40', auto parking at upper tier is 115' x 95'. One culvert " CMP. Total length of entrance drive is approx. 1844'. Continuation Sheet? State Historic Preservation Office Comments
areas. Bus parking area is 85 under paved area, a 11" x 18" National Park Service, MARO Individually Eligibla Contributes to: Property District Potantial District Not Eligibla & Doas Not	' x 40', auto parking at upper tier is 115' x 95'. One culvert "CMP. Total length of entrance drive is approx. 1844'. Continuation Sheet?
areas. Bus parking area is 85 under paved area, a 11" x 18" National Park Service, MARO Individually Eligibla Contributes to: Property District Potantial District Not Eligibla & Doas Not Contribute to Property/District X	' x 40', auto parking at upper tier is 115' x 95'. One culvert " CMP. Total length of entrance drive is approx. 1844'. Continuation Sheet? State Historic Preservation Office Concur
areas. Bus parking area is 85 under paved area, a 11" x 18" National Park Service, MARO Individually Eligibla Contributes to: Property District Potantial District Not Eligibla & Doas Not Contribute to Property/District X Insufficiently Documented,	' x 40', auto parking at upper tier is 115' x 95'. One culvert "CMP. Total length of entrance drive is approx. 1844'. Continuation Sheet?
areas. Bus parking area is 85 under paved area, a 11" x 18" National Park Service, MARO Individually Eligibla Contributes to: Property District Potantial District Not Eligibla & Doas Not Contribute to Property/District X	' x 40', auto parking at upper tier is 115' x 95'. One culvert "CMP. Total length of entrance drive is approx. 1844'. Continuation Sheet?
areas. Bus parking area is 85 under paved area, a 11" x 18" National Park Service, MARO Individually Eligibla Contributes to: Property District Potantial District Not Eligibla & Doas Not Contribute to Property/District X Insufficiently Documented,	' x 40', auto parking at upper tier is 115' x 95'. One culvert "CMP. Total length of entrance drive is approx. 1844'. Continuation Sheet?

Form Prepared By: Stephen M. Clark

NPS, MARO, CRM 10/14/93

Emoto 11 March 12 18003





Mansion Entrance Dr. & Parking Lot



NEG # LCS HAMP

Mansion Entrance Dr. & Parking Lot



Mansion Entrance Dr. & Parking Lot



NEG # LCS HAMP

Mansion Entrance Dr. & Parking Lot



NEG # LCS HAMP

Mansion Entrance Dr. & Parking Lot



NEG # LCS HAMP

Mansion Entrance Dr. & Parking Lot

Aug 1993

BA-103

PARK NAME, STATE HAMPTON NATIONAL HISTORIC SITE, MARYLAND						
STRUCTURE NAME(S): BRICK BARBECUE						
PROPERTY / DISTRICT NAME: HAMPTON NHS						
LOCATION Street Address: 535 HAMPTON LAI	NE Town / City: TOWSON					
	nty: BALTIMORE PARK Trect #: n/e					
DATE BUILT: 1948-1953 LCS:	PARK #:					
SIGNIFICANCE Netionel Stete & Reg	ione Locel					
NATIONAL REGISTER CRITERIA A	B C D					
NARRATIVE STATEMENT OF SIGNIFICANCE						
structure that may have been built dur It is a non-descript structure that has r by the Ridgely's or to the formal lands Through its lack of association	yard area of the Farm House and is a rudimentary ing the occupancy of the Farm House by John Ridgely, Jr. no known association to the later Milk Farm introduced cape designed and built for the Ridgely's. to the Ridgely Dairy operation and the formal landscape at the nificant either architecturally or historically to the overall individually or collectively.					
	Continuation Sheet?					
NARRATIVE DESCRIPTION						
cooking surface measures 2'-0" x 2'-0	Continuation Sheet?					
	OSILII SALO. O ASIL					
National Park Service, MARO	State Historic Preservation Office Comments					
Individually Eligible	Per request of NFS,					
Contributes to:	DOE deferred until					
Property Co.	DR nomination prepared					
District						
Potentiel District	EALT					
Not Eligible & Does Not Do	Not 10/26/95					
Contribute to Property/District X Co	ncur					
Insufficiently Documented,						
Treet es Eligible						
Regional Director, MARO NEFA	Stete Historic Preservetion Officer / / NPS, MARO, CRM 10/14/83					
Form Prepared By: Stephen M. Clerk	RF3, MAIO, 51 10,14/05					





NEG # LCS HAMP 005

Barbeque at Overseer's House

August 1993

	PARK NAME, STATE: HAMF	PTON NATIONAL HISTORIC SITE, MA	RYLAND	
	STRUCTURE NAME(S): BRICE	K OCTAGONAL HERB GARDEN		
	PROPERTY/DISTRICT NAME:	HAMPTON NHS		
	LOCATION Street Address: Municipality: n/	535 HAMPTON LANE /a	Town/City: TOWSON County: BALTIMORE	
_	DATE BUILT: 1970-1980	IDLCS: none	PARK #:	
	SIGNIFICANCE:	National	State & Regional	Local
	NATIONAL REGISTER CRITERI	A: A B C	D	
	foundations of the removed or	oes not relate to mansion or outbuildi ctagonal Servant's Quarters. Therefo does not possess any architectural or	re, the site may contain archeologic	structed over top of the cal significance, but the
				Continuation Sheet? N
¥.	garden club built this structure very the garden beds. At the center	o garden terrace built over foundation with radiating brick arms, emanating from the radiating arms and center gard octagon 10'4". The herb garden is lo	om circular brick center garden (radiu Ien is a sundial. The total diameter	s approx. 6') to separate of the octagonal garden
				Continuation Sheet? N
	National Park Service, MARO	State Historic Preservation Comments	on Office	
	Individually Eligible			*
	Contributes to:	V		
	Property District	Concur 💢		
	Potential District			
	Not Eligible & Does Not Contribute to Property/District	_X Do Not		
	Insufficiently Documented, Treat as Eligible			
	S	ignature 7		
ħ	Regional Director, MARO NEF Field 11 915/95	State Historic Preservation Of	ficer	





NEG # LCS HAMP

Brick Octagonal Herb Garden




NEG # LCS HAMP

Brick Octagonal Herb Garden

Aug 1993

BA-103

PARK NAME, STATE: HAME	TON NATIONAL HISTORIC SITE, MAR	RYLAND	
STRUCTURE NAME(S): ENTE	ANCE DRIVE CULVERTS		
PROPERTY/DISTRICT NAME:	HAMPTON NHS		·
LOCATION Street Address: Municipality: n	535 HAMPTON LANE	Town/City: TOWSON County: BALTIMORE	
DATE BUILT: 1950-1980	IDLCS: none	PARK #:	
SIGNIFICANCE:	National	State & Regional	Local
NATIONAL REGISTER CRITERIA	A: A B C	D	
Culvert system does n	ot relate to Hampton Mansion or Estate	. Structures have no historical or a	rchitectural significance.
			Continuation Sheet? N
DESCRIPTION			
entrance unive, although only tw	stalled by the park service after acquis to outfalls were located. The system cor re 3' square, one box is 18" square. CM	nsists of a drainage grate and box co	innected to a corrupated
National Park Service, MARO	State Historic Preservation		
	Comments		
Individually Eligible			
Contributes to: Property District Potential District	Concur <u>X</u>		
Not Eligible & Does Not Contribute to Property/District	Do Not Concur		
Insufficiently Documented, Treat as Eligible		· <u> </u>	
- Barnie Or Holds	gnature AlliA		
Regional Director, WARD NEFA	State Historic Preservation Office	cer	
9/5/95			10.5





Culverts on Entrance Drive

August 1993



NEG # LCS HAMP 003 BA-103

Culverts on Entrance Drive

August 1993



HAMP

NEG # LCS HAMP 003

Culverts on Entrance Drive

August 1993



BA-103

Culverts on Entrance Drive

August 1993



Culverts on Entrance Drive

August 1993


DETERMINATION OF SIGNIFICANCE

PARK NAME, STATE HAMPTON NATIONAL HISTORIC SITE, MARYLAND							
STRUCTURE NAME(S): PARK MAINTENANCE BUILDING							
PROPERTY / DISTRICT NAME: HAMPTON NHS							
LOCATION Street Address: 535 HAMP	TON LANE Town	/ City: TOWSON					
Municipality: n/a	County: BALTIMORE PARK	Tract #: n/a					
DATE BUILT: 1980-1990 LCS: _	n/a PARK #:						
SIGNIFICANCE National Sta	te & Regiona Local						
NATIONAL REGISTER CRITERIA A	B C	D					
NARRATIVE STATEMENT OF SIGNIFICANCE							
No association with Hampton Estate or Mansion. Structure possesses no architectural or historical significance either collectively or individually for inclusion to the National Register.							
		Continuation Sheet?					
NARRATIVE DESCRIPTION							
low-pitch gable root. Clad in vi	ertical aluminum siding. Approx. 25						
		Continuation Sheet?					
National Park Service, MARO	State Historic Preservation Office	Comments					
Individually Eligible							
Contributes to:							
Property	Concur X						
District							
Potential District							
Not Eligible & Does Not	Do Not						
Contribute to Property/District X	Concur						
Insufficiantly Documentad,							
Traat as Eligibla							
Regional Director, MARIO NEFA IN Fight, 915195	State Historic Press	arvation Officar					

Form Prepared By: Stephen M. Clark

NPS, MARO, CRM 10/14/93

1 1 1





NEG # LCS HAMP 3A-103


Park Maintenance Bldg & Storage Shed Maintenance Bldg Aug 1993




Park Maintenance Bldg & Storage Shed Maintenance Bldg Aug 1993

DETERMINATION OF SIGNIFICANCE

_		 					
PARK NAME, STATE: HAMPTON NATIONAL HISTORIC SITE, MARYLAND							
	STRUCTURE I	STRUCTURE NAME(S): PICKET FENCE					
	PROPERTY/DISTRICT NAME: HAMPTON NHS						
ı,	LOCATION	Street Address: 535 HAMPTON LANE Municipality: n/a		Town/City: TOWSON County: BALTIMORE			
	DATE BUILT:	1980	IDLCS: none	PARK #:			
	SIGNIFICANC	E:	National	State & Regional	Local		
	NATIONAL RE	EGISTER CRITERIA: A	B C	D			
	Struc	Structure does not relate to Hampton Mansion or Estate. The picket fence has no architectural or historical significance.					
	·				Continuation Sheet? N		
	DESCRIPTION	l :					
The picket fence is located southeast of the Mansion and surrounds the vegetable garden. It was piece to designate an area where the Hampton vegetable garden may have been located. The demand							
based on conjecture. Fence is approx. 73'-4" x 66'-8", total length is approx. 280'.							
à							
					Continuation Sheet? N		
	National Park	Service, MARO	State Historic Preservation Comments				
	Individually El	igible					
	Contributes to	o:	J				
	Property District		Concur X				
	Potential Di	strict					
	Not Eligible & Contribute to	Does Not Property/District X	Do Not Concur				
	Insufficiently Treat as Eligib						
Signature							
Bannie John Starle							
١	- Regiona l Dir Field //	ector, MARO NEFA Stat	Historic Preservation Office	er ·			
1	915	195	·		e on		
					237		





HAMP

NEG # LCS HAMP BA-103

Picket Fence

Aug 1993



Picket Fence

Aug 1993